

Datenblatt für Artikel: HSELDA40WP

# Üres FTTH falon kívüli doboz, sz80xma28xmé80mm, 4-szálas

RAL9010 fehér, DIS sínre szerelhető



## SCHRACK-Info

FTTH empty outlets serve as a universal interface for fiber optic installations.

They offer a high degree of flexibility when it comes to equipping and adapting the network infrastructure.

Empty outlets are an ideal solution for organizing the fiber-optic connection efficiently and ensuring a clean, well-structured installation—especially when planning for future expansions or upgrades of the network structure.

### Features

- Fiber Optic In-House-Cabling
- Offers connection options for up to 4 end devices
- The box is suitable for pre-assembled cables or for pigtails

- Flexible cable entry options
- Lid locks into place
- 2 screws, 2 dowels, and 2 shrink splice protectors included

#### Optional Accessories

##### Couplers:

- HSELSK09MR
- HSELSK09GR

##### Pigtails:

- HLP09M041P
- HLP09D041P

#### Safety information:

##### Avoid direct contact with light sources:

- Fiber optic cables—especially those with active light sources such as lasers (e.g., in optical communication systems)—can emit hazardous radiation that may damage the eyes.
- Never look directly into the light of a fiber optic cable, even if the light source is invisible to the naked eye.

##### Wear protective eyewear:

- When working with fiber optic cables, especially during tests or when using lasers, always wear safety glasses to protect your eyes from harmful radiation.

##### Handle cables correctly:

- Plug in and unplug cables only by holding the connector, and never pull directly on the cable.

##### Do not bend or crush:

- Fiber optic cables are sensitive to mechanical stress.

##### Protect from damage:

- Install cables in dedicated conduits or use protective materials to prevent physical damage.

##### Keep connectors clean:

- Fiber optic connectors must be free of dust and dirt.
- Even small particles on the connectors can significantly reduce signal quality.

##### Observe temperature limits:


- Do not expose cables to extremely high or low temperatures.
- Follow the manufacturer's specifications for the cable's maximum operating temperature.

##### Inspect regularly:

- Frequently check cables for visible damage such as cracks, bends, or signs of wear.
- Damaged cables must be replaced immediately.

## Technische Daten

|                                  |                    |
|----------------------------------|--------------------|
| Nettó szélesség (mm)             | 80,00              |
| Nettó magasság (mm)              | 28,00              |
| Nettó tömeg (kg)                 | 0,05               |
| Szín                             | RAL 9010 (hófehér) |
| Min. környezeti hőmérséklet (°C) | -40                |
| Max. környezeti hőmérséklet (°C) | 75                 |

**méretrajz: Üres FTTH falon kívüli doboz, sz80xma28xmé80mm, 4-szálás**

## Artikeltabelle

| BEZEICHNUNG                                                                                                                                                                                                                                                                                                           | BEST.NR.   |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|
| Üres FTTH falon kívüli doboz, sz80xma28xmé80mm, 4-szálas<br>RAL9010 fehér, DIS sínre szerelhető                                                                                                                                                                                                                       | HSELDA40WP |
| <b>Választható tartozék</b>                                                                                                                                                                                                                                                                                           |            |
| FTTH optikai kuplung LC/APC-Simplex, műanyag, OS2, kerámia<br>karima nélkül, zöld, porvédő, CLASSIC                                                                                                                                                                                                                   | HSELSK09MR |
| FTTH optikai kuplung SC/APC-Simplex, műanyag, OS2, kerámia<br>karima nélkül, zöld, porvédő, CLASSIC                                                                                                                                                                                                                   | HSELSK09GR |
| FTTH Optikai pigtail LC/APC 8°, 9/125µm OS2 G657.A2, 1.0m<br>Easy Strip, EC 60304 színekód, Classic 4 db-os kiserelés                                                                                                                                                                                                 | HLP09M041P |
| FTTH Optikai pigtail SC/APC 8°, 9/125µm OS2 G657.A2, 1.0m<br>Easy Strip, EC 60304 színekód, Classic 4 db-os kiserelés                                                                                                                                                                                                 | HLP09D041P |
| Optikai tisztító eszköz LC és MU<br>Használható UPC és APC csatlakozókhoz. Több mint 1000 tisztítási ciklus.                                                                                                                                                                                                          | HSELSZT001 |
| Optikai tisztító eszköz SC, ST,FC és E2000<br>Használható UPC és APC csatlakozókhoz. Több mint 1000 tisztítási ciklus.                                                                                                                                                                                                | HSELSZT002 |
| Opt. teljesítménymérő beépített lézeres fényforrással (VFL)<br>RJ45 réz kábelteszt. FIGYELEM: Ez egy 2. osztályú lézertermék. Ne nézzen a lézersugárba. A VFL port fedele mindig legyen rajta,<br>amikor nincs használatban. Optikai szálak rendszerekkel végzett munka során ajánlott lézer-védőszemüveg használata. | HSELSZT003 |